

DEPARTMENT OF ENVIRONMENT AND CONSERVATION DIVISION OF WATER POLLUTION CONTROL 6^{TH} FLOOR, L&C ANNEX, 401 CHURCH ST, NASHVILLE, TN 37243

Site (D: 47467

NOTICE OF INTENT (NOI)

for discharges of treated groundwater associated with

UNDERGROUND STORAGE TANK (UST) REMEDIATION

		This ap	oplication is f	or: 🛛 Ne	w Permit	Permit Reiss	uance	t Modification	ı		
				nitted for Permit M	Iodification provi	de the existing per	rmit tracking number: T	NG83)			
Site N	ame:	BY-LO	#1					County:	GRAI	NGER	
Street Locati	Address or	1245 B	ROADW.	AY DRIVE	, BEAN ST	ATION, TI	N	*Latitude:	36.323		
					,	<u>-</u>		*Longitude:	-83.280		
	Site ID Number						ation (topographic) map				
Owner			or legal entity v		's operation; this	may or may not b	e the same as the site nar	me or the officia	al contact nam	ie)	
	Official Contact Person Name: (individual responsible for a site) MR. MITCH ROBINSON				or a site)	Title or Position: PRESIDENT					
1	Mailing Add	ddress: OX 1241				City: MORRIST	TOWN	State: Zip: 37814-1		1241	
	Phone: (423) 586-0681					E-mail:					
	Local Contact Person Name: (if appropriate, write "same as #1") JIM WINGFIELD			•	Title or Position: President-Wingfield Environmental, Inc.						
2	Site Address: (this may or may not be the same as street address) PO BOX 8957			address)	Site City: GRAY		State: TN	Zip: 37615			
	Phone: E-mail: jimmy@wi						ingfieldenviro.	com			
Er Cl	iters Ditc ierokee L	h line tl ake nea	nat flows ar Mile 79	~100 ft. into	o unnamed		es and stream miles) that flows ~1,00	0 ft into	No.of outfalls:	1	
				, extent of contam			•	lan Cumm	. AMT		
Descri Li tro	ption and desig quid ring eating less	pump of than 5	of treatment pro extracts g gal/min.	ocess and facilities	s. r then goes	***	ective Action Pl		r stipper		
Expec	ted starting dar	e for ground	dwater treatme	nt, and estimated 1	life of remediation	n project:	diation project.				
CERT	TFICATION AT	ND SIGNAT	URE								
I certi that q persor aware	fy under penali ualified person is directly resp	ty of law that mel properly onsible for significant p	at this document y gather and e gathering the enalties for sul	valuate the inforn information, the ir	nation submitted. 1formation submi rmation, includin	Based on my inc tted is, to the best	ion or supervision in acc juiry of the person or p t of my knowledge and f fine and imprisonment	ersons who ma belief, true, acc	nage the systemate, and constant on the systemate of the system of the s	em, or those	
	E USE ONLY					<u> </u>		341	· -		
Receiv	ed Date		Reviewer		EFO		NOC Date	Trac	king No. TNG83		

Ale Chilve

JUN 2 0 2011

Submit the original of the completed and signed form to:

UST NOI Processing
Tennessee Division of Water Pollution Control
6th Floor L&C Annex, 401 Church Street

Floor L&C Annex, 401 Church Stree Nashville, TN 37243 (continued)



DEPARTMENT OF ENVIRONMENT AND CONSERVATION DIVISION OF WATER POLLUTION CONTROL 6^{TH} FLOOR, L&C ANNEX, 401 CHURCH ST, NASHVILLE, TN 37243

NOTICE OF INTENT (NOI)

for discharges of treated groundwater associated with

UNDERGROUND STORAGE TANK (UST) REMEDIATION


Impaired Receiving Stream	High Quality Water	T & E Aquatic Fauna

RECEIVED
JUN 2 0 7011
Th Division - 2017

Submit the original of the completed and signed form to:

UST NOI Processing
Tennessee Division of Water Pollution Control
6th Floor L&C Annex, 401 Church Street
Nashville, TN 37243

BY LOMARKET#1



PART B-SITE-SPECIFIC PROPOSAL

I. EXECUTIVE SUMMARY

This Corrective Action Plan (CAP) has been prepared for Coffman Oil Company, Inc., owner of the Underground Storage Tank (UST) system at the By-Lo #1 site. The By-Lo #1 site is located at 1245 Broadway Drive in Bean Station, Tennessee.

On February 19, 2003, the Division of Underground Storage Tanks (DUST) was notified that a 4,000-gallon unleaded gasoline Underground Storage Tank (UST) failed a tank tightness test. The release was suspected due to a sheen and petroleum odor identified on the standing water in the yard of an adjacent property. DUST issued a release response letter on February 20, 2003, requiring immediate action be taken to prevent further contamination and that an Initial Abatement Report (IAR) be prepared.

Following completion of initial abatement activities, DUST was notified by the adjacent property owner concerning petroleum vapors in the ambient air. The Division required surface soil excavation and the installation of an interceptor trench with groundwater treatment at the site. Startup of the system occurred on October 15, 2003. The treatment system was shut down at the direction of the Knoxville UST office on March 9, 2006. A revised Site-Specific Standard Request was approved on August 28, 2006.

Due to the groundwater contamination at the site not meeting the approved site specific standard levels, the Division has required in a May 1, 2007 letter that a corrective action plan (CAP) be completed using the July 2004 CAP Guidelines.

